

EQUIFY AUCTIONS INSPECTION REPORT

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
89051	John Deere	200CLC	2007	FF200CX506705

CAB	GOOD	FAIR	BAD	OPERATIONAL	EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY
Cab Type	CLOSED				Paint	X			
Clean	X				Sheet Metal	Minor Dents			
Seat		X			Fiberglass	X			
Seat Belts	X				Blade	N/A			
Air Ride Seat	NO				Frame	X			
Brake Type	HYDROSTATIC				Mirrors	MISSING			
Warning Lights	X				Fuel Tanks	X			
Guages	X				Cutting Edge	N/A			
Mileage	N/A				Screens	N/A			
Hours	5460				Lights	X			
Horn			X		Blade Type	N/A			
Glass		X			Hyd. Tank	X			
Controls	X				Hoses	X			
Brakes	X				Stick	X			114"
Door Controls	X				Boom	X			
Heated Mirrors	N/A				Boom Swing	N/A			
Lights	X				Aux. Hydraulics	X			
Overall Condition	X				Bucket	X			42"
					Cutting Edge	X			
					Coupler Type	N/A			
					Overall Condition	X			
Comments					Comments				
ENGINE	YES	NO	MISSING	OPERATIONAL	DRIVE TRAIN	OPERATIONAL	NON-OPERATIONAL		
Blow By	X				Drive Motors	X			
Turbo	X				Swing Motor	X			
Radiator	X				Tracks	31 1/2"			
Oil Leaks		X			Sprockets	X			
Water Leaks		X			Idlers	X			
Belts		X			Bushings	X			
Emissions Label		X			Overall Condition	X			
Exhaust	X								
Engine Make	John Deere								
Engine Model	6 Cylinder								
Fuel Type	Diesel								
Overall Condition	x								
Comments					Comments				
LOGISTICS					MISC.				
Length	33'								
Width	126"								
Height	12'								



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING
 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050
equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. As this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.