

EQUIFY AUCTIONS INSPECTION REPORT

ITEM NUMBER	MAKE	MODEL	YEAR	SERIAL NUMBER
20143	John Deere	310G	2008	T0310GX961171

CAB	GOOD	FAIR	BAD	OPERATIONAL	EXTERIOR	GOOD	FAIR	BAD	SIZE/CAPACITY
Cab Type	Closed				Axles	X			
Clean	X				Front Tires	X			12-16.5
Seat	X				Rear Tires	X			440/80-24
Seat Belts	X				Rims	X			
Air Ride Seat	NO				Lug Nuts	X			
Brake Type	Hydraulic				Frame	X			
Warning Lights	X				Paint	X			
Guages	X				Sheet Metal	X			
Mileage	N/A				Fiberglass	X			
Hours	3360				Mirrors	X			
Horn	X				Fuel Tanks	X			
Glass	X				Lift Arms	X			
Controls	X				Pins / Bushings	X			
Brakes	X				Extenda Stick	NO			
Door Controls	X				Stick	STANDARD			
Lights	X				Front Bucket	X			86"
Overall Condition	GOOD				Rear Bucket	X			25"
					Out Riggers Type	STREET			
					Cylinders	X			
					Rops	X			
					Articulation Pins	N/A			
					Hydraulic Tank	X			
					Hoses	X			
					Overall Condition	GOOD			
Comments					Comments				
ENGINE	YES	NO	MISSING	OPERATIONAL	DRIVE TRAIN	OPERATIONAL	NON-OPERATIONAL		
Blow By	MINOR				Transmission	X			
Turbo	X				Front Axle	X			
Radiator	X				Rear Axle	X			
Oil Leaks		X			Rear Axle	N/A			
Water Leaks		X			Transfer Case	X			
Belts	GOOD				Tracks	N/A			
Emissions Label	YES				Sprokets	N/A			
Exhaust	X				Idlers	N/A			
Fuel Type	DIESEL				Track Bushings Turned	N/A			
Engine Model	404STT				4 X 2	N/A			
Engine Make	John Deere				4 X 4	X			
A/C Compressor					Overall Condition	GOOD			
Overall Condition					Comments				
Comments									
LOGISTICS					MISC.				
Length	28'								
Width	86"								
Height	10'								



EQUIPMENT LENDING | COMMERCIAL INSURANCE SERVICES | HEAVY EQUIPMENT AUCTIONS | APPRAISAL SERVICES | COMMERCIAL REAL ESTATE LENDING
 777 Main Street, Suite 3900, Fort Worth, TX, 76102 | (844) 334-0050
equifyauctions.com

INSPECTION SERVICE DISCLAIMER: This inspection has been performed by Equify Auctions for general guidance and is intended for providing our buyers with general information on a non-binding basis. Equify Auctions has made every effort to insure that the information in this report is accurate and reliable. as this is intended to provide support for our customer's errors may occur from time to time. In no event will Equify, LLC or their affiliated parties be liable for any direct or indirect or consequential loss or damage that has any connection with this report. All information in this publication is made with no warranties of any kind for the content, material, or functionality accessed in this publication. This inspection is intended to identify observable defects. Equify Auctions will not be taking samples, or using technical or ultrasonic equipment to complete this inspection. The inspection was not completed the day of the sale and all conditions obtained in this report represent only the day that this inspection was performed.