



# 2011 KOMATSU PC138US LC-8

Year	Serial Number	Stock Number
2011	KMTPC189E01026051	20562

Hours	Location
7883	Wills Point, TX 24280 I-20 Frontage Rd Wills Point, Texas USA 75169



Category Specifics	
Stick Condition	Good
Swing Bearing	Good
Boom Condition	Good
Bucket Size	38
Bucket Type	ROCK TOOTH
Bucket Condition	Good
Counterweight	Good
Pins/Bushings	Good
Emergency Shut Off	Good

General Appearance	
Guards/Covers/Steps	Good
Hood/Grill/Fenders	Good
Glass/Mirrors	Good
Doors	Good
Cab Type	ENCLOSED, A/C & HEAT
Paint	Good
Seat	Good
Heater	Yes
Steering Wheel Play	No

General Appearance Interior	
A/C	Yes
A/C Condition	Good

Engine	
Engine Manufacturer	KOMATSU
Engine Model	SAA4D95LE-5-A
Engine Serial Number	516419
Horse Power	97
Blow-By	No
Oil Leaks?	No
Smokes	No
Turbocharger	Yes
Coolant Leaks	No
Coolant Levels	Good

Powertrain	
Transmission Type	HYDROSTATIC
Transmission Condition	Good
Linkage	Good
Final Drives	Good

Chassis	
Pad Size	24
Steering Linkage	Good

Electrical	
Batteries	Good
Warning Lights Work	Yes
Gauges Work	Yes
Lights Work	Yes

Hydraulics	
Hoses	Good
Cylinder Rods	Good
Pumps	Good
Hydraulics Leak	No